



# Technical Bulletin



Old (yellowish) internal lubricant



New (whitish) internal lubricant

## Our Trimmer Series PJ 11 - 63 and Volume Control PJ 85 Just got better!

**Quality comes from the inside.**

**S**onion's quality philosophy continuously adds more value to our products for the purpose of exceeding market quality requirements.

Therefore, we are pleased to announce that we have achieved a more reliable trimmer series and PJ 85 with our new and improved internal sealant. The sealant inside the trimmer and PJ 85 will provide more resistance to heat, solvents and cleaning agents used during handling.

The sealant can be identified from the inside of the component by its more whitish appearance. Please see pictures above. This change was implemented on June 6th, 2006 and will have no influence on the part numbers that you order today.

The lubricant is well proven in Sonion's other EMC products. However the trimmers and PJ 85 have been specifically qualified according to our internal Sonion Qualification Procedures.

Please do not hesitate to contact us, should you have any questions or need further information regarding the above. You may also contact your local Sales Representative for electromechanical components or [sonion.cqs@sonion.com](mailto:sonion.cqs@sonion.com)

Dan Lundahl  
Quality Manager  
Medical Division