



Technical Bulletin



Old version



New version

CS Sockets Improved Contact Reliability

Sonion is pleased to announce that we have added more value to our CS Socket series for the purpose of adapting to the market quality requirements.

We have improved the contact reliability between the Socket and the CS Plug, extending the ground pin length by 0.1mm.

This is improving the overall reliability in regards to connection and contacting between the Socket and the Plug and thereby minimizing a potential risk of bad contact during handling of the component as well as improving the overall component robustness.

Consequently, this change will have no influence on the part numbers that you order today. The improvement was implemented in February 2009. It is possible to identify improved parts by the visual appearance inside the Socket – improved ground pin has a more flat edge on the top than the previously.

Should you have any questions or need further information to the improvement described above, please do not hesitate to contact your local Sales representative or Customer Quality Service (CQS), Medical Division in Roskilde, Denmark.

Dan Lundahl
Quality Manager
Medical Division